

# **KEKB Beam Transport Line Issues**

**2001 February 24**



**Toshihiro Mimashi**

# **1. Operation status**



## **1.1 Transport Line**



		Transmission	Inj. effciency	Inj. Rate
e+	best	80%	100%	1.8 mA/s
	typ.	70%	80%	1.4 mA/s
e-	best	100%	100%	4.0 mA/s
	typ.	95%	80%	2.8 mA/s



- (1) Inj. efficiency strongly depends on the mask positions.**
- (2) Inj. rate depends on the energy spread of the beam as well.**
- (3) Initial setup of beta match between Linac and BT typically holds one month.**
- (4) Empirical beta match from BT to ring sometimes helps injection efficiency.**




Main Application Area










Main Application Area



**(5) Poor transmission of positrons stems from the loss of low energy tails at the ECS bends.** To accommodate lower energy particles in the aperture of the bends, smaller bend angle is adopted than the nominal value, which produces 5mm excursion at the center of ECS bends. Since the first bend of ECS is common to electron beam this manoeuvre also generates 10mm excursion of electron beam, which sometimes results beam loss when the energy spread is accidentally large.

**In order to cure this situation we plan to install a small dipole after the first ECS bend, which serves as an energy adjuster. Also in order to decrease the loss of the positron beam replacement of the chamber with wider one is considered.**





## **2.Issues**

### **2.1 An issue pointed out at the last MAC meeting**

**“The electron injection efficiency to HER is reported to have a lower value of 30-40%.**

**Therefore, the committee would like to recommend that the KEKB team carry out further studies on this subject.”**

**→ “The electron injection efficiency becomes 80-100%”**



**(In the last summer, one of the masks in the IP region was removed.)**





### **2.2 Other issues (Nothing is so serious)**





**(1)Septum magnet vacuum rise during long time injection.**

**(2)Time jitter of kicker thyratons become bigger than before.**

**(3)Beam based alignment**







### **3.Upgrade plans**

#### **3.1 R&D status for the Bypass Line**

**R&D of the permanent-magnet dipole is underway.**

- (1) 1-m 0.25T dipole was constructed.**
- (2) Field strength was 10% lower than the design value.**
- (3) Temperature dependence of the field strength is approximately  $-5 \cdot 10^{-4}/\text{deg}$  that means temperature coefficient of the Fe-Ni alloy compensator is 10% smaller than the specification.**

#### **3.2 Beam position monitor upgrade for 2-bunch acceleration**

- (1) Add another VXI digital oscilloscope**
- (2) Reorganized signal delay**

