

Stability Upgrade of Injector Linac

Injector linac Group

H. Kobayashi

Upgrade of Linac Stability

Basic parameters (energy, current etc.):

→ reported in the previous talk

Stability (especially for primary electron beam for positron beam production)

→ need improvements


problems

- sudden change of beam orbit, current energy spread etc.
- many faults
- poor reproducibility


Causes of instability of linac

- SHB1 microwave source
- SHB2 microwave cavity
- A-1 (the first unit of the linac) s-band microwave amplifier
- microwave monitor
- cooling water
- stabilize high power pulse voltage etc.

$$A1 \Delta\phi = 0'$$




$$A1 \Delta\phi = -2'$$




$A1 \phi = 0^\circ$



$A1 \phi = 0^\circ$ (変動)





$A1 \phi = +2^\circ$



A1 $\theta = 71.4^\circ (0^\circ)$


+2°

-2°




File Edit Measurement Correction Steering Orbit Window

03/02/1999 18:02:35 Help




File Edit Measurement Correction Steering Orbit Window

03/02/1999 18:03:27 Help



SHB1 258.1°




03/02/1999 17:30:01 Help

rms = 1.465 mm
 max = 3.565 mm
 @ SP1062
 min = -4.122 mm
 @ SP124
 @ SP17C4

rms = 1.184 mm
 max = 4.122 mm
 @ SP124
 min = -3.401 mm
 @ SP154


1.718 nC
 @ SP17C4

meas -> ref stat -> ref



Err [Err] Measurement Correction Steering Orbit Window

03/02/1999 17:37:43 Help



rms = 0.27 mm
 max = 3.55 mm
 @ SP144
 min = -4.001 mm
 @ SP17C4

rms = 1.362 mm
 max = 5.198 mm
 @ SP144
 min = -5.405 mm
 @ SP174

Oe/bunch (nC)


mode: e' e' e' range: DX Auto + Fix (3) DY Auto + Fix (3) Oe Auto + Fix (13) e' e' 10 Replot

meas stat ref meas-ref stat-ref

meas -> ref stat -> ref

Hard Copy

SHB1 256.1°



03/02/1999 17:21:40 Help



rms = 1.567 mm
max = 5.332 mm
@ SPR062
min = -5.151 mm
@ SP17C4

rms = 1.233 mm
max = 3.168 mm
@ SP124
min = -4.145 mm
@ SP164

Qe/bunch
1.716 nC
@ SP17C4

meas -> ref | stat -> ref

SHB1 256.1°



measured 03/02/1999 17:21:40

rms = 1.567 mm
max = 5.332 mm
@ SPR062
min = -5.151 mm
@ SP17C4

rms = 1.233 mm
max = 3.168 mm
@ SP124
min = -4.145 mm
@ SP164

Qe/bunch
1.716 nC
@ SP17C4

meas -> ref | stat -> ref

1/19(火) e+3.5GeV

1/20(水) e+3.5GeV

1/21(木) e- 8GeV

1/22(金) e- 8GeV

1/23(土) e- 8GeV

KLA1SB に空調の風が当たらないようにした=>A1 位相変わった

入射突然不調(BT 放射線)=>原因不明、ECS KL58 位相調整で回復

早朝：SHB2 パワーダウン (2 回)

昼間：SHB2 パワーダウン (パルス幅調整で復旧)

SHB1 アンプ調整 10 分、5Hz だと Y513 (放射線) 急上昇

朝、リング RF 周波数設定ミスで全クライストロン OFF

=>SHB1 アンプチューニングずれる

切替直後、QD/F_22,21/2 落ちる

SHB1:Att.Phase Local Controller の Amplitude 設定がゼロ (原因不明)

SHB2:同様の現象再発、パワーフィードバックはずれる

SHB2:再発

コミッションング中故障・不具合頻度 (11.30~1.25)

SHB: 16 回

SHB1: 7 回

SHB2: 6 回

IVR: 1 回

IΦA: 1 回

TrigII: 2 回

サイラトロン: 1 回

フィードバック: 4 回

水温: 3 回

多数クライストロントリップ: 7 回

タイミング: 1 回

DeQ コントローラ: 1 回

Qmag: 8 回

電子銃: 2 回

Ky の電子銃と Es の電圧 → 特定の電子銃
A1 の 0.8kV は上げろ。

Sub-harmonic Buncher (SHB1)

114MHz 10kW amplifier


○two power tubes: 7651 cascade amplifier

○has been used since 1985

○very many failures: still have not found cause of this series of trouble

replace with a new solid state amplifier (this summer)

SHB 114 MHz 励振回路構成図



Cavity for Sub-harmonic Buncher (SHB2)

571MHz resonant cavity

tune drift (seems temperature change of inner conductor)

reflection of microwave at input coupler

input coupler will be replaced in March

replace with newly designed one (cooling channel for inner conductor)

this summer




図4 SHB 空洞の断面図.

A-1 sub-booster

2856MHz Klystron drive microwave (600 watt solid state amp.)

drive only A-1 klystron without SLED
(the first klystron in injector linac)


no phase lock loop

affected with temperature shift of klystron gallery

replace with a newly designed one (April to May)
with phase lock loop


現在の

A1Driver_{1ΦA}



改造後のの

A1Driver



sub-boosters

2856MHz Klystron drive microwave

60kW klystron to drive 8 klystrons

found that large phase shift caused by temperature change of klystron gallery and by a mechanical shock

fixed suspicious point(4th March) :expect improvement

microwave monitor

very powerful tool for diagnostics

started operation at end of January this year

installed only in A, B, and a part of C sectors

install this microwave monitor in all sectors up to end of April

KLY.A-3

Signal Selector

Cont. On


QUIT

Peak Hold

(vxia-4)

SLED.Pf (Amplitude) : SLED.Pf (Phase)

SLED.Pf (Amplitude)



KLY Pf

36.3

KLY Ph

0.0


VSWR

1.01

Peak [v]

1.686


SLED.Pf (Phase)



Phase [deg.]

276

RF MONITOR SYSTEM




RF unit No.1

RF unit No.2

99. 2. 21(10)

16:46



stabilize cooling water

Temperature of accelerating structures increased by 1 degree and affected beam stability.

Cause →lack of capacitor of heat exchange

stabilize temperature of cooling water for accelerating structures finished January (1 degree to 0.04 degree).

Recently, heat load for cooling water for klystrons increased then the same problem as that of cooling water for accelerating structures occur

Cause →lack of capacitor of heat exchange

stabilize that for klystrons during March by same process














図4 印加電圧の変化率と位相の変化 ($V=300kV$)



加送管系冷却水温度


Aセツタ -	1.2セツタ -
Bセツタ -	3.4セツタ -
	5セツタ -



Klypton系冷却水温度

A 779-	1.2 779-
B-C 779-	3.4 779-
	5 779-

セツ B.C
 KLY 冷却水



stabilize high power pulse output (injection part)

High power pulse voltage (klystrons, electron gun) is stabilized by De-Q circuit.

→ compression factor is roughly 1/10


If the stability of ac power supply is $\pm 3\%$ then $\pm 0.3\%$ for output

If klystron modulator has same stability


→ about ± 1.2 degree phase shift.

start the test in the gun modulator using AVR

200 RV 高圧変動 5 秒毎



高圧変動 10 秒毎



AC 200V 変動 (%)

