# Fire at Nextef

Tetsuo ABE For Nextef team

The 23rd KEKB Accelerator Review Committee Meeting

2019-07-09


## Missions of <u>Nextef</u> (<u>New X</u>-band <u>Test Facility</u>)


- X-band high-gradient accelerating structure collaborative development under agreement between CERN and KEK (ICA-JP-0103)
- Development of efficient and cost-effective high-gradient normal conducting accelerating structures as a US-Japan cooperative program (mainly with SLAC)

## Nextef: New X-band Test Facility (11.4 GHz)

In Shield-A


for testing Normal-Conducting High-Gradient Accelerating Structures







### X-band Prototype Structures Tested at Nextef / Shield-A

T18 →Quad → TD18→T24→TD24R05→TD24R05 →T24THU→TD24R05 →Deflector →TD24R05 → TD26CC → DCS → T24-K1 (terminated by the fire)




## Fire on April 3<sup>rd</sup>, 2019





Before the fire

#### After the fire



#### Burnt modulator











## Operation History in April 3<sup>rd</sup>, 2019

## Continuous Operation Started for High-Power Testing of a Newly Installed Accelerating Structure




#### Just before the fire, History of the operation and INTLK messages




## **Operation Panel with the final INTLK messages**

#### At 21:55 on April 3rd, 2019




# X-band Modulator

## Nextef modulator configuration



#### Modulator Drawing

(PFN: Pulse Forming Network)




## INTLK sensors in the cubicle of the X-band modulator


Smoke sensor

located at the center of the ceiling

Temperature sensor (Threshold: 40 degC) located at the edge of the ceiling



## Long-term operation of the modulator



The Nextef modulator had been operated below the spec.


## What is the cause of the fire?

- No deterioration of the modulator performance observed
- The most likely cause is puncture of the <u>plastic-case capacitors</u> (although there is no direct evidence).
  - Fire occurred at other facilities using modulators with plastic-case capacitors.
  - At Nextef, such puncture occurred twice.



250 mm


#### Puncture of plastic-case capacitors in the Nextef modulator




## Parameters of the capacitors Safety-oriented

ltem		Unit	Nextef (PFN2)	ATF (after improvements(*))	Injector Linac (S-band)
Case	Size	mm	110 x 140 x 250	150 x 130 x 380	Ø162 x 260
	Volume	cm <sup>3</sup>	3850	7410	5359
	<b>Material</b>		<b>Plastic</b>	<mark>Plastic</mark>	Ceramics
	Puncture protection		None	None	<mark>Equipped</mark>
Material of electrode			Al	Al	Al
Material of dielectric			Polypropylene	Polypropylene	Polypropylene + low- density paper
Type of insulating oil			Plant oil (flash point: 230 degC)	Plant oil (flash point: 230 degC)	Synthetic oil (flash point: 148 degC)
Weight		kgf	4.7	~10	10.0
Capacitance		nF	30.5	46	15.5
Charging voltage in op.		kV	38	44	43
# of elements			20 to 22	25	21
Electrode gap		μm	36	36	47
Potential gradient in op.		V/µm	<mark>52.8</mark>	<mark>48.9</mark>	<mark>43.6</mark>
Repetition rate in op.		Hz	50	3	50
Lifetime	Design	hour	3.9x10 <sup>5</sup>	1.0x10 <sup>5</sup>	1.5x10 <sup>5</sup>
	<mark>Estimate</mark>	hour	-	-	<mark>2.8x10<sup>15</sup></mark>
Time to failure		hour	~35,000	> 10,000 (No failure)	> 150,000 (No failure)

### Puncture protection mechanism in the capacitors for Injector Linac





# (\*) Significant improvements made for plastic-case capacitors used at ATF

- The winding method to form a capacitor from films was improved to reduce the appearance of wrinkles and make the electrode gap uniform.
- The potential gradient in operation was reduced to make the lifetime longer.
  - 75 **→** 48.9 V/µm


etc.

- lifetime  $\propto$  (potential gradient)<sup>n</sup> (n >> 1)
- The fabrication process was improved to suppress foreign matter inclusion into the insulting oil.
  - Foreign matter inclusion was observed in the previous versions of plastic-case capacitors.
  - Foreign matter inclusion is known to induce partial discharge.
- Various sizes were reviewed and re-optimized.

In the Nextef modulator, we used the previous versions of plastic-case capacitors fabricated before the abovementioned improvements were made.

## Recovery

## All the devices, equipments and instruments have been removed for cleaning the experimental hall. (Taken at the end of Jun., 2019)



## Nextef system improvements under consideration

- 1. No plastic case, use metallic or ceramic case for capacitors.
- 2. Reduce potential gradient in capacitors
- **3.** Routine check of capacitors on size, capacitance, loss tangent, etc.
- 4. Install monitoring the modulator by TV cameras
- 5. The smoke detection in the cubicle of the modulator should be integrated in the fire alarm system of the building.
- 6. If smoke is detected, stop cooling fans attached on the modulator ceiling.
- 7. Fire extinguisher should be installed inside the modulator, and activated automatically.
- 8. Location and sensitivity of smoke sensors should be optimized.
- 9. Temperature sensors inside the modulator should be optimized.

Nextef recovery protocol proposal after modulator-related INTLK activation

- Check INTLK messages, recorded pulse shapes, and videos recorded by TV cameras
- 2. Input check marks to make sure all of the above items are checked
- 3. Temporally reset by physical switch located near the modulator
  - Remote reset is then impossible<sup>(\*\*)</sup>.
  - By this temporal reset, we can resume the operation, and proceed to the next step.

#### 4. Confirm normal operation

- Locally check the situation by seeing the operation for half or a minute in a close distance from the modulator
- Then we can push the main reset button
- Unless this main reset button is pushed within a defined period (e.g. 60 s), HV is forced to be OFF.

(\*\*) At ATF, remote reset of modulator-related INTLK has been impossible from the beginning.

## Summary

- Nextef is a high-gradient test facility for normal-conducting accelerating structures.
  - Operated since 2008, basically 24-hours, ~4,000 hours/year
  - Achieves enough performance of X-band prototype structures to meet the CLIC specification.
- Fire in the modulator on April 3<sup>rd</sup>, 2019
  - Severe damage to only Nextef but also Injector Linac
  - The most likely cause is puncture of the plastic-case capacitors.
  - Recovery process underway
  - More safe capacitors will be used for the next Nextef modulator.
    - Routine check of capacitors on size, capacitance, loss tangent, etc.
  - Nextef control system will be reconstructed in a safety-oriented manner.
  - Monitoring and INTLK will be stepped up.