

# Vacuum System Status

T. Ishibashi, KEK

on behalf of KEKB Vacuum Group



## Contents

- Updates of vacuum system before Phase-3
- Present status
  - vacuum scrubbing
  - electron cloud effect in LER
  - problems
- Summary and plans

# Updates of vacuum system - ECE

- Countermeasures for Electron Cloud Effect(ECE)
  - Approximately 91% of the drift spaces of LER were covered by magnetic field in the beam direction with permanent magnets or solenoid coils before Phase-3.
  - In Phase-2, approximately 86% of that were covered as presented the previous KEKB Review.


Type-1 unit




Permanent magnets

Iron yoke (plate)


Magnetic field of Type-1 unit  
Typical strength ~ 60 G



Magnetic free  
1/2500/2RF, 3.6 A  
 $\delta_{\max}=1.2$



Type-1 unit  
1/2500/2RF, 3.6 A  
 $\delta_{\max}=1.2$



# Updates of vacuum system - collimators



- Installation of new beam collimators
  - LER: D02H1, D02H2, D03H1, D06V1
  - HER: D01H3
- Moved a collimator from D06H4 to D06H1 in LER

H: horizontal  
V: vertical

D02H1 collimator




Schematic drawing of the horizontal collimator



# Updates of vacuum system - collimators

- Trouble: water leakage from a movable jaw of D02H1 collimator.
  - Changed to a backup jaw.





# Updates of vacuum system – jaw damage

- LER: A huge beam loss and pressure burst happened near D02V1 with a QCS quench at 11:20 June 25<sup>th</sup>, 2018 in Phase-2. Stored current was 728 mA. The tungsten tips of the jaws were damaged. After that we were not able to run the luminosity mode because of high backgrounds in this condition. → move the collimator
- HER: A huge beam loss and pressure burst happened near D01V1 with a QCS quench at 11:20 June 9<sup>th</sup> in Phase-2, 2018. Stored current was 766 mA. Jaws were damaged. After that we were able to run the luminosity mode in this condition.

Pressure bursts near D02V1




Photo of a D02V2 bottom jaw.





Photo of a D02V2 top jaw.




# Updates of vacuum system – jaw damage

- Jaws of D02V1 top, bottom and D01V1 top were changed to new ones in the presence of Radiation Science Center.
  - D02V1:  $\sim 10 \mu\text{Sv/h}$
  - D01V1:  $\sim 30 \mu\text{Sv/h}$
- The damaged tungsten is likely to be crumbly by the embrittlement.
  - plan to change the material from tungsten to tantalum



Photo of a D01V1 top jaw.



# Updates of vacuum system


- others
  - Installation of longitudinal feedback kicker in LER.
  - Changed septum beam pipes to reduce the leakage field into MR.
  - Installation of bellows chambers with SR mask in HER downstream of IP because temperature rise was observed in a stainless chamber caused by SR in QCS.
  - Abort system by pressure burst besides collimators to avoid the jaw damage.
  - etc.



# Present Status – vacuum scrubbing



- MR

- Maximum stored beam current in Phase-3: HER 940 mA, LER 830 mA
- Beam dose in Phase-3: HER 536.3 Ah, LER 500.3 Ah





# Present Status – vacuum scrubbing (LER)

- The  $dP/dI$  in MR has been smoothly decrease by the vacuum scrubbing.
  - In LER, the  $dP/dI$  curve in Phase-3 is similar with that in Phase-2 because some regions were exposed to the atmosphere for vacuum works. The  $dP/dI$  at the end of Phase-3 is below that of Phase-2.






# Present Status – vacuum scrubbing (HER)

- The  $dP/dI$  in MR has been smoothly decrease by the vacuum scrubbing.
  - In HER, the  $dP/dI$  in SuperKEKB is below that in KEKB at the final stage by the historical effect.



# Present Status – vacuum scrubbing (DR)

- DR
  - Beam dose: 3.9 Ah.
  - No trouble.




# Present Status – ECE


R14.1: Continue the experimental investigation of electron cloud and the conditioning of the TiN coating. Implement the proposed test with permanent magnets on the antechamber of the drift beampipes.

- In Phase-1, vertical beam size blow up and nonlinear behavior of pressures from  $I_d \sim 0.1$  by ECE were observed in LER.
  - The current linear density ( $I_d$ ) is the bunch current divided by the bunch spacing.
- The threshold was relaxed to  $I_d \sim 0.2$  by an installation of permanent magnets on bellows chambers.
- A threshold in KEKB without solenoids was approximately  $I_d = 0.04$ .

ECE in Phase-1 with/without permanent magnets in bellows chambers




2019/7/8





23rd KEKB Review

Permanent magnets and iron yoke on a bellows chamber



# Present Status – ECE

- Permanent magnets were installed on ~86% of the drift spaces before Phase-2.
- The blowup was not observed by  $I_d=0.4$  in Phase-2.
- Approximately 91% of the drift spaces were covered with them before Phase-3.
- The blowup was not observed by  $I_d=0.55$  in Phase-3.
  - The design value is  $I_d=0.72$  (3.6 A, 2500 bunches, 2 RF-bucket spacing)



courtesy of H. Fukuma

# Present Status – problems

- Collimators are quite effective to reduce BG.
- Collimator damage
  - LER: A huge beam loss and pressure burst happened near D02V1 with a QCS quench at 22:11 June 9<sup>th</sup>, 2019 in Phase-3. Stored current was 660 mA. The tungsten tips of the jaws were damaged. After that we were not able to run the physics mode because of high backgrounds in this condition.
  - This is a similar situation as a QCS quench event in Phase-2, and we need the detailed analysis about this incident. One of the candidates that caused this incident is a dust event.

Photo of a bottom jaw in D02V1 taken from a view port






Photo of a top jaw in D02V1 taken from a view port



Pressure bursts near D02V1 collimator




# Present Status – problems


- Collimator damage

- At the same time, pressure bursts were observed in a beam pipe with a clearing electrode. → a dust event caused the beam energy loss?
- We are plan to knock the beam pipes in wiggler section by next commissioning.
- Any materials would melt if whole beams hit the jaw.
  - Need fast abort to avoid the damage!

Pressure bursts in NIKKO wiggler section



Maximum temperature induced by beam hit  
( $1 \times 10^{12}$  e-/pulse (16 mA), effective bunch radius: 50  $\mu$ m, R.L. = 0.5)





# Present Status – problems

- Dust events


- The number of dust events has been decreasing with the operation time.

- Aging effect by low current operation
- Quick abort before a burst occurs
- Dust drop by a knocker


- However, it can cause beam energy loss.

→ drop dusts using the knocker before next commissioning

→ proposed an aging operation with high current before a physics run




3rd KEKB Review




# Present Status – problems

- Temperature of IP bellows chamber in HER in Phase-3, which is between a QCS beam pipe and an IP chamber.  $\sim 60^{\circ}\text{C}$  (850 mA, 3.06RF, 1578 bunches) . This happened in 1 of the 4 bellows chambers.
- The similar heating on an another one had also been seen in Phase-2. It was changed to new one before Phase-3.
- The RF shield is a conventional fingers type. Fault of the electrical contact?  
 → We have a plan to replace it with new one in this summer shutdown.




Detached IP bellows chamber after Phase-2




Discharged mark

- This finger was off after the installation and put it back before Phase-2.
- This happened in 1 of the 4 chambers.



# Present Status – problems


- Pressure upstream of IP in LER.
    - Vacuum component is dominant for BG in LER.
    - Especially, pressures near D02V1 and D02H1 are high.
      - D02H1 collimator had a water leakage trouble before Phase-3, so it could raise the pressure.
- try baking these collimators and beam pipes in tunnel



# Present Status – problems

- Pressure upstream of IP in LER.
  - Vacuum bump study using NEG pump heating in Phase-3
  - D02, D06, D12 seem to be sensitive to BG.

courtesy of H. Nakayama



# Summary and plans

- Vacuum scrubbing is going well.
- Countermeasures for ECE in LER are quite effective.
- Problems:
  - Collimator damage
  - Dust events
  - BG in derived from vacuum
  - IP bellows chamber heating
- Near Future Plans:
  - Change the damaged collimator(D02V1 bottom) in the summer/winter.
  - Knock beam pipes in LER.
  - Try baking collimators in tunnel.
  - Change IP bellows chamber in this summer shutdown.
  - Add a vertical collimator at D06V1 in LER in the winter shutdown.