Injector Linac Status

Masanori Satoh (KEK, Acc. Lab.) for Injector Linac Group


Contents


- Injector overview
- HER injection beam (rf e- gun) status
- LER injection beam (e+, FC) status
- Beam abort caused by abnormal injection beam
 - Abnormal orbit (pulsed magnet issue)
 - Abnormal energy (rf failure)
- Summary and plan


2020/7/11

Injector: Simultaneous top-up to five rings

- Photocathode RF gun for HER injection
- Thermionic gun for LER (via DR), PF, PF-AR








Hybrid laser system for rf gun


Three Oscillators (two of them are backup)

 Yb doped fiber and Neodymium (Nd) doped laser crystal.










1st + 2nd laser line:laser line:e- beam bunch length

~ 10 ps (FWHM)



UV laser beam profile


e- source

R. Zhan, SuperKEKB review, 2019 Optics layout in the tunnel

HER injection beam (rf e- gun) status


- HER injection w/ only rf gun since Mar. 11th, 2019.
- Laser system has no significant fault.
- In summer shutdown of 2019, photocathode (Ir₇Ce₂) was replaced by new one (Ir₂Ce) for aiming at better quantum efficiency (Qe).
 - Discharge, frequent VSWR, gradual decrease of bunch charge
- In the last winter shutdown, photocathode was replaced (Ir₂Ce_{=>} Ir₇Ce₂). However, bunch charge decreased gradually.
 - Laser cleaning for recovering Qe
 - Bunch charge feedback

2020/7/11




Laser cleaning / Focused laser size

- 2nd Laser only
- Scan using focused laser beam without RF









2020a,b

HER injection beam (rf e- gun) status


- Laser cleaning for recovering Qe works fine.
- Bunch charge feedback works fine to keep bunch charge constant.
- Diffractive optical element (DOE) was installed and tested for transverse laser beam shaping (flat top).
 - It could be help for low emittance beam w/ high bunch charge.
- Laser position feedback will be prepared in this summer shutdown.







First beam test result w/ DOE (Jul. 1st)

Reshaping of RF gun laser



Without DOE






- Designed elliptical laser beam patten is realized by use of DOF
- Total loss for DOE chamber set is about 25% (acceptable)
- Laser beam stability is also improved


Inter pulse laser cleaning


- Laser cleaning works fine for recovering Qe.
- Usually, it takes 30 min. ~ 1 hour. (every two weeks).
- Fast switching scheme between beam on (rf on) and laser cleaning (rf off) was tested. (Jul. 2nd, 2020)



e- beam emittance (~ 1 nC) εx,y ~15 μm at SectorB, SectorC


- Emittance growth at BT2 in both directions.
- Emittance could be increased at around solenoid section in Sector1.
- (*) More detail will be given by Iida san.





Steering magnet and BPM in solenoid section


- There is no BPM and steering magnet between e+ target and 16_5 unit.
- DC steering (x4) and BPM (x4) will be installed in this summer shutdown.
- It could be help to cure e+ beam loss and e- beam emittance growth.




e+ source setup

Positron target and capture section






e+ bunch charge trend



LER injection beam status

- Bunch charge
 - Stable and enough bunch charge in this stage
 - Primary e-: 11 nC (from gun), 9 nC (on W target)
 - e+: 2 nC (after target), 1.2 nC (linac end), 1.2 nC (BT)
- Flux concentrator (FC)
 - Previous FC was damaged by large discharge during PhaseII. It was removed in Sept. 2018.
 - Current FC was installed in Jan. 2019.
 - 2 ~ 3 kA operation current (design 12 kA) for stable operation. no significant fault. Requirements for material of the FC head are
 - Good brazing characteristic
 - High yield strength even after brazing
 - High electric and thermal conductivity
 - New FC made of Cu-alloy (NC50: Cu-Si-Ni) has been tested w/o fault (~ 12 kA).
- New FC will be installed in summer shutdown of 2020 for aiming at design 2020/7/11operation current.


After large discharge...



Slit gap got narrow. Not possible to apply high voltage unless the gap will be expanded. After large discharge



FC assembly, base summary



- *Base 7, 8, 9 (head : Cu \rightarrow NC50, return yoke : SS400 \rightarrow permendur)
- **Base 8, 9 Shape optimization (insulation, leakage magnetic field)


red: operation

blue: spare

black: test bench

Y. Enomoto

Test result of new FC: 2020/1 - 2020/6




During long term test, no trouble (discharge and vacuum pressure problem)

FC base 7 test: ~ May 2020 FC base 8 test: June 2020 ~

FC (base 5) 12 kA beam test (Jul. 2nd, 2020)


FC current vs positron yield




Comparison FC base

	Material	Shape	Remark	For e-	For e+
Base 5 (in operation)	OFC + SS400	Old design	12 kA in beam line large slit gap	Δ	0
Base 7	NC50 + permendur	Old design	4.5 months test	0	O+ *
Base 8	NC50 + permendur	New design (optimized)	Cooling water leakage was found. (already fixed and tested during 4 days)	©	O+ *


All FC bases achieve 12 kA in test stand. (*) return yoke (permendur) makes higher magnetic field.






e+ beam emittance (~ 1 nC)

- e+ beam emittance in linac and BT1 are smaller than current goal.
- Emittance growth at BT2 in both directions.
- (*) More detail will be given by Iida san






Abnormal injection beam could cause MR abort

- Abnormal beam orbit
 - Pulsed magnet misfire (Sector3-Sector5)

- Abnormal beam energy
 - Klystron down
 - RF phase trip
 - RF pulse shortening (klystron discharge)


2020/7/11 25

Pulsed magnet misfire events




Beam abort caused by pulsed magnet misfire

• 49 events in 2020a, 2020b.



Pulsed magnet misfire events


- ~ 100 misfire/day in Feb./Mar. (16 controllers)
- Main control software and event receiver driver were replaced by improved one (Apr. 9th~). # of misfire events decreased to almost zero.
- Misfire appears again (Jun. 10th 22:30~16th 3:23).



network trouble?

(*) including all misfire events (even no beam)

Beam abort caused by injection beam w/ abnormal energy



Horizontal position (mm)


Vertical position (mm)


Bunch charge (nC)

Abnormal energy beam

- Collimator at ECS of linac end -

- Klystron down or rf phase trip could cause energy change.
- In the case of e+ beam, ECS (in linac end) can correct it to a certain extent. Beam can go through BT and into MR.
- To prevent such beam, collimator will be installed in this summer maintenance.





• RF gun (e- beam) Summary and plan

- - no significant fault
 - Bunch charge feedback works fine.
 - Laser cleaning can cure degradation of Qe. Laser cleaning during beam operation was tested.
 - Diffractive optical element (DOE) was installed and tested for transverse laser beam shaping (flat top).
 - Laser position feedback will be implemented in this summer shutdown.
- Flux concentrator (e+ beam)
 - no significant fault
 - New flux concentrator will be installed for higher e+ bunch charge in this summer shutdown.
 - Steering magnet and BPM will be installed inside solenoid section in this summer shutdown.

Summary and plan (cont'd)

- Beam abort caused by bad quality beam (orbit, energy)
 - Pulsed magnet misfire (orbit)
 - Control software have been improved.
 - Install collimator at ECS (linac end) in this summer shutdown.
- Vertical pulsed bends and chambers will be replaced new one for 50 Hz operation of thermionic e- gun (LER, PF, PF-AR) in this summer shutdown.
- Beam quality issues
 - Emittance growth at BT2
 - Reproducibility
 - Low emittance w/ high bunch charge (~ 2 nC)

Backup

2020/7/11 33

Linac Beam Parameters for KEKB/SuperKEKB

Stage	KEKB (final)		Phase-I		Phase-II		Phase-III (interim)		Phase-III (final)	
Beam	e+	e–	e+	e-	e+	e-	e+	e–	e+	e–
Energy	3.5 GeV	8.0 GeV	4.0 GeV	7.0 GeV	4.0 GeV	7.0 GeV	4.0 GeV	7.0 GeV	4.0 GeV	7.0 GeV
Stored current	1.6 A	1.1 A	1.0 A	1.0 A	_	_	1.8 A	1.3 A	3.6 A	2.6 A
Life time (min.)	150	200	100	100	_	_	-	-	6	6
	primary e- 10		primary e- 8	1	0.5	1	2	2	primary e- 10	
Bunch charge (nC)	→ 1	1	→ 0.4						→4	4
Norm. Emittance	1400	310	1000	130	200/40	150	150/30	100/40	<u>100/15</u>	<u>40/20</u>
(γβε) (μmrad)					(Hor./Ver.)		(Hor./Ver.)	(Hor./Ver.)	(Hor./Ver.)	(Hor./Ver.)
Energy spread	0.13%	0.13%	0.50%	0.50%	0.16%	0.10%	0.16%	0.10%	<u>0.16%</u>	0.07%
Bunch / Pulse	2	2	2	2	2	2	2	2	2	2
Repetition rate	50 Hz		25 Hz		25 Hz		50 Hz		50 Hz	
Simultaneous top-up injection (PPM)	3 rings (LER, HER, PF)		No top-up		Partially		4+1 rings (LER, HER, DR, PF PF-AR)		4+1 rings (LER, HER, DR, PF, PF-AR)	


2020/7/11 34

Feedback loops (1)

KEKB e- Jarc F.B Parameter Graph

6.67063687124e-05


- Beam energy feedback (J-ARC, LTR, ECS, BT)
 - J-ARC $\overline{(e-, e+)}$
 - DR (e+)
 - Linac end
 - -BT (e-, e+)
- Energy stability at BT line < 0.025%



Feedback loops (2)


- Beam orbit feedback
 - J-ARC (e-, e+)
 - − e+ target upstream (e-, e+)
 - Sector2 (e-)
 - Sector3-5 (e-)
 - Linac end, BT end (e-, e+)

Sector3-5 FB ON



Feedback loops (3)

- RF phase feedback has been newly implemented.
- Quick recover from tunnel work (after maintenance or trouble recovery)




常時レーザークリーニング

• 1st-PumA, 2nd-PumpB




Beam emittance example (~1 nC) w/ multiple wire scanners



Pulse to pulse


e-/e+ beam switching

- Pulsed steering magnet control e- beam orbit.
- Low emittance e- beam goes through a hole at center of beam line.




for low emittance e- beam

Qe of photocathode (Ir7Ce2, Ir2Ce)




Simultaneous beam operation (w/ thermionic and rf e- gun)

• Stable simultaneous top up injection to 4 storage rings (HER, LER, PF, and PF-AR) w/ thermionic gun, rf gun, pulsed magnets.




Previous software structure

In some events, LabVIEW/EPICS IOC communication is delayed or failed.




New software structure (Apr. 9 ~)

- NI VISA based EVR driver (w/o EPICS IOC for EVR control) (H. Saotome)
- Most part of control core (LabVIEW) was rewritten (Y. Enomoto)




Measured emittance

e+ beam (Phase3.2(6.Nov.2019))



e- beam (Phase3.2(4.Dec.2019))



Phase3.3	e+	e-
γεχ [μm]	150	100
γεу [μm]	30	40
σδ [%]	$0.16(1\sigma)$	0.1(1σ)

Emittances increase

- DR \rightarrow Sector3
- BT1 \rightarrow BT2


Beam study will be continued

Emittances increase


- $C \rightarrow Sector3$
- BT1→BT2


Beam study will be continued

Dispersion measurement and correction





- Horizontal dispersion leakage from J-ARC causes the beam position jitter.
- Applying fudge factors to quads in J-ARC, dispersion is well corrected.





Vertical emittance vs. HER Injection efficiency






1. Injection efficiency and background

The injection efficiency increased as emittance decreased by tuning day by day.

Phase3.2 These efficiencies are calculated at the low current beam in the HER. 2019c(Autumn) → The effect of <u>Touschek</u> lifetime can be neglected. 300 250 200 150 100 $\beta y^*=1.0mm$ γεv=144 ± 24μm: 40% γε $v=105 \pm 14$ μm: 55% ν εν=83 \pm 23μm: 75% 100 [] γεν=66 \pm 13μm: 100% BW135 [mRad/s] 156 [% Energy spread became better [mRad/s] 12^h 12^h 12^h $0^{h}0^{m}$ $o^h o^m$ $0^{h}0^{m}$ 12^h0^m0^s $o^h o^m$ 211/24/2019 11/25 11/26 11/27 11/28







2020/7/11 50

Monitors

- Beam position monitor (x 103)
 - Four strip line electrodes (x 97)
 - Measurement precision ~ 10 μm
 - Eight strip line electrodes (x 6) (J-ARC, LTR x2, PF BT, HER BT, LER BT)
- Profile monitor (x 104)
 - Al₂O₃/CrO₃ (AF₉95R, Demarquest Co.). (t: 1 mm, 0.1 mm), YAG:Ce (t: 0.1 mm)
- Wire scanner (WS) (x 6)
 - SectorA, B, C, 2, 3, 5
- Streak camera (ST) (x 2)
 - SectorA, €, 3
- RF monitors for klystron, SLED, acc. structure








Pulsed magnet system


- Pulsed quads (x 28) (w/ ceramic duct) and steering (x 36) were installed at Sector3 to Sector5 in 2017 (on movable girder).
- Pulsed bend, additional quad and steering were installed in 2018 summer and winter shutdown.
- PXIe based control system (Windows 8.1, LabVIEW, EPICS) have worked fine w/o any serious trouble.

• Power supply stability: 0.01% (24 hours)



e+ source setup 2

FC head + BC + target = FC assembly



Movable girder for accelerating structure


- Six movable girders have been installed in Sector3 (in summer shutdown of 2019).
 - Four 2-m-long accelerating structures are mounted on one girder.
- It could help to suppress emittance growth due to misalignment.




リーク箇所




リークテストでは水色の枠 部がピンポイントで反応する 目視では亀裂や穴は判別できない





FC Base8 after repair



Pressure and FC (base8) current after repair

